



# REGIONAL DISTRICT NORTH OKANAGAN

## Silver Star Water (SSW) Water Quality Report for June 2022

The following is the water quality summary for the Silver Star Water (SSW) Utility.

### 1. Sources

Not all of Silver Star's water sources are utilized year round; the system is constructed so that the sources can be brought on line based on demand. As Silver Star is primarily a winter resort, the highest water demands occur during November to March. SSW has nine water sources used for domestic use: Well 1, Well 2, Well 3, Well 4, Well 5, Well 10, Well 12, Paradise Reservoir and Vance Reservoir.

The surface water sources, Paradise and Vance Reservoirs, are metered in the Mid T water treatment plant as one volume; it is not possible to separate the volumes of each reservoir. The surface water sources were not in use for the month of June.

Table 1 summarizes the results of the raw water entering the treatment process. This is a blend of sources depending on demands in the system. This results in data variation throughout the year. Tables 2 summarizes the results for the untreated water of the wells. Wells 4, 5, 10, and 12 have not been used this season.

**Table 1 Mid T Raw Water Monitoring**

Parameter	Laboratory		# of Samples	# of Deviations <sup>1</sup>	Min	Max	Average
E.coli	Caro	MPN/100 mL	4	-----	<1	<1	<1
Total Coliform	Caro	MPN/100 mL	4	-----	<1	<1	<1
Turbidity	Grab sample	NTU	8	-----	0.17	0.54	0.31
Turbidity	SCADA <sup>2</sup> Daily Average	NTU	29 <sup>3</sup>	-----	0.04	0.13	0.09

<sup>1</sup>SSW WQ Deviation Response Plan – Free Chlorine <0.20 mg/L Turbidity >1.0 NTU

<sup>2</sup>SCADA: Supervisory Control and Data Acquisition.

<sup>3</sup>Data from one day (June 28) was not included in this report due to a lightning strike impacting instrumentation.

**Table 2 Mid T Raw Water Monitoring – Wells**

Parameter	Laboratory		# of Samples	# of Deviations <sup>1</sup>	Min	Max	Average
Turbidity	SCADA <sup>2</sup> Daily Average	NTU	30	-----	0.02	2.04	0.43

## 2. Treatment Plant

SSW has a treatment plant, the Mid T Water Treatment Plant (MTWTP). The MTWTP uses a dual disinfection process of Ultra-violet (UV) disinfection and chlorine. Chlorine is added after UV treatment to ensure contact time for the removal of viruses. Tables 3, 4 and 5 summarize the results for chlorine, bacterial, turbidity, calculated contact time, and UV transmittance (UVT).

**Table 3 Mid T Water Treatment Plant**

Parameter	Laboratory		# of Samples	# of Deviations <sup>1</sup>	Min	Max	Average
Free Chlorine	SCADA <sup>2</sup> Daily Average	mg/L	30	-----	1.55	1.67	1.60
Free Chlorine	Grab sample	mg/L	8	-----	1.57	1.69	1.62
Total Chlorine	Grab sample	mg/L	8	-----	1.65	1.78	1.70
E.coli	Caro	CFU/100 mL	8	-----	<1	<1	<1
Total Coliform	Caro	CFU/100 mL	8	-----	<1	<1	<1
Turbidity	SCADA <sup>2</sup> Daily Average	NTU	30	-----	0.09	0.63	0.20
Turbidity	Grab sample	NTU	8	-----	0.15	0.35	0.23

<sup>1</sup>SSW WQ Deviation Response Plan – Free Chlorine <0.20 mg/L Turbidity >1.0 NTU

<sup>2</sup>SCADA: Supervisory Control and Data Acquisition.

**Table 4 Contact Time (CT)**

Parameter	Days Monitored	Min	Max	Average
<b>Days 99.9% achieved</b>	13	100%	100%	100%

99.9% is 3-log removal for Giardia

**Table 5 Ultra-violet (UV) Disinfection**

Parameter	Laboratory	Days Monitored	Min	Max	Average
UVT	SCADA <sup>1</sup> Daily Average	28 <sup>2</sup>	92%	98%	94%

<sup>1</sup>SCADA: Supervisory Control and Data Acquisition.

<sup>2</sup>Two days of data not included in this report due to instrumentation maintenance. On these days, UVT was confirmed to meet standards using a handheld device.

### 3. Distribution

Table 6 summarizes the results for chlorine, turbidity and bacterial for the distribution system from the following sites: Pinnacles, Grandview, Firehall, and Maintenance Building. The monthly water volume used at Silver Star was 6,509 m<sup>3</sup>.

**Table 6 Distribution**

Parameter	Laboratory		# of Samples	# of Deviations <sup>1</sup>	Min	Max	Average
Free Chlorine	Grab sample	mg/L	30	-----	1.14	1.59	1.49
Total Chlorine	Grab sample	mg/L	30	-----	1.20	1.67	1.57
E.coli	Caro	CFU/100 mL	9 <sup>2</sup>	-----	<1	<1	<1
Total Coliform	Caro	CFU/100 mL	9 <sup>2</sup>	-----	<1	<1	<1
Turbidity	Grab sample	NTU	30	-----	0.12	0.42	0.27

<sup>1</sup>SSW WQ Deviation Response Plan – Free Chlorine <0.20 mg/L Turbidity >1.0 NTU

<sup>2</sup>Treatment Plant bacterial samples are included in the required monthly bacterial sampling amounts as per Drinking Water Protection Regulations Schedule B.

### 4. Customer Calls and Notifications

Customer calls within the Silver Star Water Utility service area are tracked and recorded. There was 1 customer call in June. Table 7 summarizes the customer calls during the month.

**Table 7 Customer calls for the month**

# of Calls	Type of Call	Issue/Inquiry	Investigation	Comments
1	Inquiry	Water pooling near curb stop	Yes	Investigation found the pooling water was a water service leak.

### 5. Operational or Maintenance Activity

Operational activities within the Silver Star Water service area are tracked and recorded. There was 12 distribution operational activities in June. Table 8 outlines the distribution operational and maintenance activities during the month.

**Table 8 Monthly Operational Work and Maintenance**

NUMBER OF LOCATIONS	TYPE OF WORK
0	Hydrant Maintenance
9	Water Service Locate
0	Water Main Break Repair
0	Water Service Install
0	Water Turn On/Off
0	Water Curb Stop Repair
2	Water Meter Inspection
0	Water Meter Maintenance
1	Water Meter Replacement
0	Water Meter Manual Read